



P 557-420-2297 Glen Canyon Unit--Colorado River Storage Project.
Workmen of Merritt-Chapman and Scott Corporation operate Eimco
loader in the right foundation tunnel. Contract No. 14-06-D-2403;
Specs. No. DC-4825. 6/2/58 A. E. Turner



P 557-420-2307 Glen Canyon Unit--Colorado River Storage Project.
Left keyway of the dam. Left foundation tunnel can be seen near lower platform of ladder sections.
Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825.
6/2/58 A. E. Turner



P 557-420-2330 Glen Canyon Unit--Colorado River Storage Project.
Excavation in right keyway of the dam showing ladders for access to the work. Foundation tunnel can be seen at right of platform extending to right of ladders. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825.
A. E. Turner



557-420-03251 Glen Canyon Unit--Colorado River Storage Project.
Right foundation tunnel at elevation 3,247 $\pm$. Contractor: Merritt-
Chapman & Scott Corporation, Contract No. 14-06-D-2403.
Specs. No. DC-4825. 1/22/59 A. E. Turner



P 557-420-03843 Glen Canyon Unit--Colorado River Storage Project.
Pot holes and flutes in the sandstone uncovered along the left side of the dam foundation excavation. Contractor: Merritt-Chapman & Scott Corporation, Contract No. 14-06-D-2403. Specs.
No. DC-4825. 5-29-59 A. E. Turner



P 557-420-04017 Glen Canyon Unit--Colorado River Storage Project.
Excavation for the dam foundation in the river bottom showing eroded rock. Contractor: Merritt-
Chapman and Sockt Corporation, Contract No. 14-06-D-2403. Specs. No. DC-5825.
7-17-59

A. E. Turner



557-420-04326 Glen Canyon Unit--C.R.S.P.
Progress of excavation for the dam foundation in the river bottom. Contractor: Merritt-Chapman
and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 1-28-60 A. E. Turner



P 557-420-04361 Glen Canyon Unit--C.R.S.P.
Progress of excavation for the dam foundation in the river bottom. Contractor: Merritt-Chapman
and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 2-4-60 A. E. Turner



P 557-420-04382 Glen Canyon Unit--G.R.S.P.
Looking downstream in the river bottom area. Note water seeping through downstream coffer-
dam to sump. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403.
Specs. No. DC-4825. 2-11-60 A. E. Turner



P 557-420-04405 Glen Canyon Unit--C.R.S.P.

Excavation in the river bottom for the dam foundation. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825.

2-18-60 A. E. Turner



P 557-420-04441 Glen Canyon Unit--C.R.S.P.
Progress of excavation in the river bottom for the dam foundation. Contractor: Merritt-Chapman
and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 2-25-60 A. E. Turner



P 557-420-04474 Glen Canyon Unit--C.R.S.P.
Looking downstream at progress of operations in the river bottom. Contractor: Merritt-Chapman
and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 3-3-60 A. E. Turner



P 557-420-04475 Glen Canyon Unit--C.R.S.P.
Looking upstream at operations in the river bottom for the power plant structure site and the dam foundation. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403.
Specs. No. DC-4825. 3-3-60 A. E. Turner



P 557-420-04483

Glen Canyon Unit--C.R.S.P.

Looking downstream at progress of operations in the river bottom. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 3-10-60 A. E. Turner



P 557-420-04536 Glen Canyon Unit--C.R.S.P.
Contractor's concrete sump and excavation for power plant structure in the inner gorge.
Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.
3-22-60 A. E. Turner



P 557-420-04561 Glen Canyon Unit--C.R.S.P.
Looking downstream at excavation for the dam foundation in the river bottom. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825.
3-31-60

A. E. Turner



P 557-420-04642 Glen Canyon Unit--C.R.S.P.
Looking downstream at excavation for the dam foundation and for the power plant in the river
bottom. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403.
Specs. No. DC-4825. 4-7-60 A. E. Turner




P 557-420-04731 Glen Canyon Unit--C.R.S.P.
Power plant excavation and base of right keyway. Five penstock support footing excavation sites in center. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825. 4-21-60 A. E. Turner



P 557-420-04683 Glen Canyon Unit--C.R.S.P.
Looking downstream at dam foundation and powerplant structure excavation. Contractor: Merritt-Chapman and Scott Corporation. Contract No. 14-06-D-2403. Specs. No. DC-4825.
1. 11. 60 A. E. Turner



557-420-04764 Glen Canyon Unit--C.R.S.P.
Looking upstream at excavation in the river bottom for power plant and dam foundation.
Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.
4-28-60 A. E. Turner



P 557-420-04765 Glen Canyon Unit--C.R.S.P.
Looking downstream at excavation in the river bottom. Excavation for power plant structure complete except for minor trim. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.
4-28-60 A. E. Turner




P 557-420-04771

Glen Canyon Unit--C.R.S.P.

Looking into the river bottom and at the base of the right keyway. Excavation for penstock support footings can be seen through the center of photograph. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs. No. DC-4825.

4-28-60

A. E. Turner



P 557-420-04778

Glen Canyon Unit--C.R.S.P.

Excavating for concrete cut-off wall just upstream of the upstream sump. This is part of contractor's diversion and care of river activities. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

4-29-60

A. E. Turner



P 557-420-04794

Glen Canyon Unit--C.R.S.P.

Looking upstream at excavation for dam foundation in the river bottom. Drills in foreground are working on penstock support footings. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-5-60

A. E. Turner



P 557-420-04795

Glen Canyon Unit--C.R.S.P.

Looking downstream at excavation in the river bottom for the dam foundation and power plant.

Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-5-60

A. E. Turner



P 557-420-04797

Glen Canyon Unit--C.R.S.P.

Looking downstream at progress of excavation in river bottom for dam and power plant.

Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs.

No. DC-4825.

5-12-60

A. E. Turner



P 557-420-04798

Glen Canyon Unit--C.R.S.P.

Looking upstream at progress of excavation in the river bottom. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825. 5-12-60 A. E. Turner



P 557-420-04799

Glen Canyon Unit--C.R.S.P.

View of excavation in river bottom showing progress on support footings for penstocks 1 through 7. Track being laid for transfer cars under batch plant. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-12-60

A. E. Turner



P 557-420-04838 Glen Canyon Unit--C.R.S.P.
Looking down at the excavation area in the river bottom and on the right side of the canyon.
Penstock support footings through left center. Excavation for ground mat in Unit Bays 1 and 3.
Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs.
No. DC-4825. 5-19-70 A. E. Turner



P 557-420-04848

Glen Canyon Unit--C.R.S.P.

View of right side of dam foundation and power plant areas. Excavation for ground mat in Unit Bays 1, 3 and 4. Penstock support footings between the two areas. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-26-60

A. E. Turner



P 557-420-04849

Glen Canyon Unit--C.R.S.P.

"B" hole grouting operations in Block 6 through 10. Final cleanup and washing in upstream section of dam foundation. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-26-60

A. E. Turner



P 557-420-04891


Glen Canyon Unit--C.R.S.P.

Final cleanup in downstream dam foundation area. Footings for penstocks 4 and 5 under construction in bottom. Contractor: Merritt-Chapman and Scott Corporation - Contract


No. 14-06-D-2403, Specs. No. DC-4825.

5--26-60

A. E. Turner



P 557-420-04892 Glen Canyon Unit--C.R.S.P.
Laying ground mat in Unit Bay 3. Contractor: Merritt-Chapman
and Scott Corporation. Contract No. 14-06-D-2403, Specs.
No. DC-4825. 5-26-60 A. E. Turner



P 557-420-04893

Glen Canyon Unit--C.R.S.P.

Steel dowels in place on the 3109 bench in Unit Bay 1. Penstock support footing 1-C at right.

Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403. Specs.

No. DC-4825.

5-26-60

A. E. Turner



P 557-420-04793

Glen Canyon Unit--C.R.S.P.

Looking down into the power plant and dam foundation areas in the river bottom. Excavation for penstock support footings through left center of photograph and reinforcing steel is being placed in footing 2-B and 2-C. Contractor: Merritt-Chapman and Scott Corporation, Contract No. 14-06-D-2403, Specs. No. DC-4825.

5-5-60

A. E. Turner